



Ktunaxa Nation Council
7825 Mission Road
Cranbrook, BC V1C 7E5
tel: 250-489-2464
fax: 250-489-2438

visit us at:
www.ktunaxa.org

Request for SEALED BIDS – VEHICLE FOR SALE

Scope	2009 Subaru Impreza up for purchase by Bid
Request for Bids Issued By	Ashley Skjonsby – Ktunaxa Nation Council, Facilities Assistant
Issue Date	July 6th, 2022
Closing Date & Time	July 15th, 2022 at 3:30 pm

KNC Contact Information & Questions	All enquiries related to this Sealed Bid including any requests for information, questions, and clarification, are to be directed to: kncfacilities@ktunaxa.org KNC will respond if time permits. Information obtained from any other source is not official and should not be relied upon.
Delivery of Bids	Submissions will be accepted in the following formats: <ol style="list-style-type: none">1. Completed & Signed Vehicle Bid Form2. Submitted to kncfacilities@ktunaxa.org before the closing date and time
Notification	For those bidders which have not been contacted by end of business day on July 18th, 2022 , will serve as notice that their submission was unsuccessful.
Submissions	Only an individual with sufficient signatory authorization may sign on the Vehicle Bid Form, included in this package.




Ktunaxa Nation Council
7825 Mission Road
Cranbrook, BC V1C 7E5
tel: 250-489-2464
fax: 250-489-2438

visit us at:
www.ktunaxa.org

Table of Contents

1. Detailed Vehicle Description & Pictures.....	2
2. Vehicle Inspection Report.....	3
3. Additional Terms and Conditions	3
4. Vehicle Bid Form.....	4

1. Detailed Vehicle Description & Pictures





2. Vehicle Inspection Report

A vehicle inspection was completed for this vehicle on March 28th, 2022 by Subaru of Cranbrook. The inspection report, invoices for recent work that has been completed, and an estimate for recommended repairs is attached to this Request for Sealed Bids.

3. Additional Terms and Conditions

- a) Submissions to this Sealed Bid must be sent to the Ktunaxa Nation Council Society (KNC) via email, as specified above.
- b) Prices are in Canadian dollars and for pickup at the Ktunaxa Nation Council Government Building at 220 Cranbrook St N, in Cranbrook BC.
- e) The KNC reserves the right to accept or reject any or all bids in the best interest of the KNC or that is less than the minimum bid price posted.
- g) Terms of payment shall be Net 14 days from the date of notification to the successful bidder.
- h) Any bid not complying with the Sealed Bid requirements may not be considered.
- i) All vehicles are sold as is, and the KNC does not warrant the condition of any vehicle sold.



Ktunaxa Nation Council
7825 Mission Road
Cranbrook, BC V1C 7E5
tel: 250-489-2464
fax: 250-489-2438

visit us at:
www.ktunaxa.org

VEHICLE BID FORM

VEHICLE VIN#: JF1GH61659H809138

VEHICLE DESCRIPTION: White 2009 Subaru Impreza

SEALED BIDS WILL BE ACCEPTED UNTIL: 3:30 PM on July 15th, 2022.

THE MINIMUM BID PRICE FOR THIS VEHICLE IS: \$2,000.00 CAN.

BID AMOUNT: \$ _____

YOUR NAME (print): _____

ADDRESS: _____

HOME PHONE #: _____

BUSINESS PHONE #: _____

CELL #: _____

YOUR SIGNATURE: _____

It is understood that said vehicle is being sold 'AS IS'. The purchaser agrees to indemnify the Ktunaxa Nation Council from any claims associated with the use of said vehicle. It is further understood that no warranty of any nature in connection with said vehicle is expressed or implied.

The Ktunaxa Nation Council Society (KNC) reserves the right to accept or reject any or all bids in the best interest of the KNC or that is less than the minimum bid price posted. The winning bidder will be contacted by phone as to the outcome of their bid after the closing date.

Payment by the winning bidder will be due within 14 days of notification, by cash, cheque or EFT to the KNC. Otherwise, the vehicle may be sold to the next bidder.

All vehicles are sold as is, and the KNC does not warrant the condition of any vehicle sold.

All bids must be submitted on this bid form.

All bids must be submitted via email to kncfacilities@ktunaxa.org with the subject title "Vehicle Bid".



SO # 419018

SERVICE ORDER



Printed 03/28/2022 11:45:06 AM CUSTOMER COPY - ** IN PROGRESS ** User KAYDEE Page 1

Customer No 71185 KTUNAXA NATION COUNCIL HEALTH DEPT 220 CRANBROOK ST N CRANBROOK, BC V1C 3R2 Home Bus (250) 420-2756 Cell (250) 464-5286 Today Email accountspayable@ktunaxa.org Term CHARGE	Advisor Allison McLeay Shop S1 Priority Promised 03/28/2022 5:00 PM Opened 03/28/2022 8:37 AM Cashiered Tag Location PO #
---	--

License No 919RJF Year 2009 Vehicle ID No JF1GH61659H809138 Engine Size	Odometer In 189956 Make SUBARU Model IMPREZA Selling Dealer	Odometer Out 189962 Model No Extended Warranty Fleet #	InServ Date 08/13/2009 Stock No S09138 Colour WHITE Delivery Date 08/13/2009
--	---	--	---

Request	Description	Job	CSR	Status
02	ONE HOUR SAFETY INSPECTION	1	991169	Original
Labour	Description	Type	Amount	
02	ONE HOUR SAFETY INSPECTION	C	130.00	
Rate	130.00			
Technician	991253 - Logan Jones			
Cause	Inspection			
Correction	Completed one hour inspection Tire tread depth 8mm Set tire pressures 33/32psi Inspected brake pads with tires off/calipres on, front 9mm rear 7mm Battery test 616/640 CCA *Cracking of drive belt, replace* *Found minor cracking on timing belt, replacement due at 168k* *Rear wiper blade torn, replace* *Cracking of the front lower control arm rear bushings, replace + 4WA* *Leaking from the trans. cooler line, replace clamp and topped fluid* *Play in the front sway bar bushings, replace* *Poor function of the LF signal light*			
		Parts Total		0.00
		Labour Total		130.00
		Request Sub-total		130.00

Request	Description	Job	CSR	Status
02	TKC-19 RECALL	2	991169	Original
Labour	Description	Type	Amount	
02	TKC-19 RECALL	W		
Part	Description	Shp	Bin	Type
98279FG07B	RECALL AIR BAG MODULE	1	J3	W
Technician	991253 - Logan Jones			
Cause	TKC-18 OP CODE A182-031 PAYS 1.6 OPTION#9 CLAIM TYPE R			
Correction	Removed and replaced the airbag as per recall. Old: WJJ3K042191 New: WJJT0K00EYH			
		Parts Total		0.00
		Labour Total		0.00
		Request Sub-total		0.00

Request	Description	Job	CSR	Status
02	CUSTOMER CONCERN OF LEFT FRONT SIGNAL BULB POOR FUNCTION. WAS REPLACED 4/28/21	3	99564	Approved

ALL ITEMS ARE SUBJECT TO P.S.T.

P.S.T. # 1101-3732

THANK YOU FOR BRINGING YOUR CAR TO US FOR SERVICE

OUT INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE: _____ SIGNATURE: _____

PARTS AND
SERVICE HOURS:
MONDAY—FRIDAY
7:30AM—5:00 PM



SO # 419018

SERVICE ORDER



Printed 03/28/2022 11:45:07 AM **CUSTOMER COPY - ** IN PROGRESS **** User KAYDEE Page 2

Customer No 71185
KTUNAXA NATION COUNCIL HEALTH DEPT
220 CRANBROOK ST N
CRANBROOK, BC V1C 3R2
Home **Bus** (250) 420-2756
Cell (250) 464-5286 **Today**
Email accountspayable@ktunaxa.org
Term CHARGE

Advisor Allison McLeay **Promised** 03/28/2022 5:00 PM **Tag**
Shop S1 **Opened** 03/28/2022 8:37 AM **Location**
Priority **Cashiered** **PO #**

License No 919RJF	Odometer In 189956	Odometer Out 189962	InServ Date 08/13/2009	Stock No S09138
Year 2009	Make SUBARU	Model IMPREZA	Model No	Colour WHITE
Vehicle ID No JF1GH61659H809138	Selling Dealer	Extended Warranty	Delivery Date 08/13/2009	
Engine Size		Fleet #		

Labour	Description	Type	Amount
02	CUSTOMER CONCERN OF LEFT FRONT SIGNAL BULB POOR FUNCTION. WAS REPLACED 4/28/21	C	0.00
Rate	130.00		0.00
Technician	991253 - Logan Jones		0.00
Cause	Removed bulb for inspection of bulb and socket. Both appear in good condition. Applied stabilant 22A to connections and re-installed bulb. Confirm good operation.	Request Sub-total	0.00
Correction	Normal function of bulb with application of stabilant.		

Labour	130.00
Parts	0.00
Supplies	0.00
SUB-TOTAL	130.00
GST	6.50
PST	9.10
TOTAL INVOICE	145.60

ALL ITEMS ARE SUBJECT TO P.S.T.

P.S.T. # 1101-3732

THANK YOU FOR BRINGING YOUR CAR TO US FOR SERVICE

OUT INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER.
DATE: _____ SIGNATURE: _____

PARTS AND SERVICE HOURS:
MONDAY—FRIDAY
7:30AM—5:00 PM

MULTI-POINT INSPECTION FORM

03/28/2022
DATE OF SERVICE419018
R.O. NUMBER

CUSTOMER NAME

PHONE

YEAR/MODEL

KILOMETERS

VIN

CUSTOMER SIGNATURE

DATE



SUBARU

Requires Immediate Attention

Checked and OK

Requires Further Attention

Not Applicable

Maintenance Schedule

☐ OK

Check Factory-Scheduled Maintenance Interval

Open Recalls/Campaigns

☐ Yes ☒ No

Recall #: _____

Recall #: _____

Recall #: _____

Recall #: _____

Interior Inspection

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|---|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Cabin Air Filter |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Door Latches/Power Lock Operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Windshield Wiper Condition/Washer Operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Parking Brake: <input checked="" type="checkbox"/> Mechanical <input type="checkbox"/> Electronic |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake Pedal & Master Cylinder Operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Clutch Pedal & Master Cylinder Operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Seat Belt Operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Instruments, Gauges, Warning Lights _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | SUBARU STARLINK™ Connected Services |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Horn Operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Exterior Lighting Operation
(headlamps, foglamps, signals, tail & brake lights, reverse lamps) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Heating, Ventilation, AC System Operation
(hoses/lines/leaks) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Glass/Power Window Operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Rearview & Side Mirror Operation (auto-dimming) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | 12V Outlet(s) Operation |

Underhood Inspection

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|---|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Accessory Drive Belt(s) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Radiator/Coolant System/Hoses (condition/leaks) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine Air Filter |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Hood Latch |

Fluid Level Inspection

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|
| OK | Filled | | Attention Required |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine Oil |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Coolant |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Power Steering Fluid (Non-EPS only) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Transmission Fluid |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Front Differential Oil |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Rear Differential Oil |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake/Clutch Fluid |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Washer Fluid |

Battery Inspection

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|-----------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Terminals/Cables |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Battery(ies) Test/Condition |

Test Code: 616 CCA
640

Technician's Comments/Additional Recommendations:

* see work order.

Drive Components, Suspension & Exterior Inspection

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Shocks/Struts |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Suspension & Chassis Components/Bushings/Ball Joints |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Steering System (rack/tie rods/pump/lines) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Axles/CV Boots |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Prop Shaft/U-joints |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Exhaust System (damage, loose parts, leaks) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Transmission (linkages/clutch hydraulics) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine/Transmission (damage, fluid leaks) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine/Transmission Mounts |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Front/Rear Differentials |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake Hoses/Lines |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Calipers/Slides (condition, movement) |

Driver Side Rear

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|----------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake Pads <u>7</u> mm |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Pad/Caliper Movement |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Rotor Condition _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tire Tread <u>8mm</u> <u>32"</u> |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Wear Pattern _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tire Pressure* <u>32</u> PSI |

Driver Side Front


- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|----------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake Pads <u>9</u> mm |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Pad/Caliper Movement |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Rotor Condition _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tire Tread <u>8mm</u> <u>32"</u> |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Wear Pattern _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tire Pressure* <u>33</u> PSI |

Brake Pad Thickness

- | | | | | | |
|-------------------------------------|---------------|-------------------------------------|---------|-------------------------------------|----------|
| <input checked="" type="checkbox"/> | Less than 3mm | <input checked="" type="checkbox"/> | 3mm-6mm | <input checked="" type="checkbox"/> | Over 6mm |
|-------------------------------------|---------------|-------------------------------------|---------|-------------------------------------|----------|

☒ Visual Brake Inspection Performed | Wheels: ☐ On ☒ Off

Exterior Body Damage



Passenger Side Rear

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|----------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake Pads <u>7</u> mm |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Pad/Caliper Movement |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Rotor Condition _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tire Tread <u>8mm</u> <u>32"</u> |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Wear Pattern _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tire Pressure* <u>32</u> PSI |

Passenger Side Front

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|----------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake Pads <u>9</u> mm |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Pad/Caliper Movement |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Rotor Condition _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tire Tread <u>8mm</u> <u>32"</u> |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Wear Pattern _____ |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tire Pressure* <u>33</u> PSI |

Spare Tire/Repair Kit 60 PSI | Lug Nut Torque 90 ft-lb☒ Tire Set Matches

- | | | | | | |
|-------------------------------------|-----------------------|-------------------------------------|-------------------------|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Under 3/32" remaining | <input checked="" type="checkbox"/> | 3/32" - 5/32" remaining | <input checked="" type="checkbox"/> | 6/32" remaining |
|-------------------------------------|-----------------------|-------------------------------------|-------------------------|-------------------------------------|-----------------|

*Tire pressure is set to factory-recommended specifications

☒ Alignment Recommended☐ Wheel Balance Recommended



EST# 14849

SERVICE ESTIMATE
CUSTOMER COPY



Printed 03/28/2022 11:14:59 AM

User KAYDEE Page 1

Customer No 71185	Advisor Kaydee Zielke (99564)	Est Date 03/28/2022	Tag
KTUNAXA NATION COUNCIL HEALTH DEPT 220 CRANBROOK ST N CRANBROOK, BC V1C 3R2	Location	Expiry Date 04/27/2022	
Home Bus (250) 420-2756	License No 919RJF	Odometer In 187753	Stock No S09138
Cell (250) 464-5286 Today	Year 2009 Make SUBARU	Model IMPREZA	Delivery Date 08/13/2009 InServ Date 08/13/2009
Email accountspayable@ktunaxa.org	Vehicle ID No JF1GH61659H809138	Selling Dealer	Colour WHITE
			Extended Warranty

Request	Description				Job	Type
TB	TIMING BELT- NON TURBO				1	C
Labour	Description			Type	CSR	Amount
TB	TIMING BELT- NON TURBO			C	99564	325.00
Part	Part Description	Req	Bin	Type	Price	Amount
13028AA231	BELT-TIMING	1	WALL2	CRO	128.99	128.99
13033AA042	ADJ AY-BELT TENS	1	B01D07	CRO	237.99	237.99
SCI541006	BEARING	1	B02D09	CRO	43.99	43.99
13073AA190	IDLER COMPL-BELT	1	B01D07	CRO	77.99	77.99
13085AA080	IDLER CP-BELT,NO2	1	B01D07	CRO	115.99	115.99
Request Total						929.95

Request	Description	Job	Type			
R&R	REMOVE AND REPLACE FRONT LOWER CONTROL ARM BUSHINGS	2	C			
Labour	Description	Type	CSR	Amount		
R&R	REMOVE AND REPLACE FRONT LOWER CONTROL ARM BUSHINGS	C	99564	364.00		
Part	Part Description	Req	Bin	Type	Price	Amount
20414FG020	RUB BUSH STAB	2	B01D08	CRO	5.99	11.98
Request Total						375.98

Request	Description				Job	Type
R&R	REMOVE AND REPLACE FRONT SWAY BAR BUSHINGS				3	C
Labour	Description			Type	CSR	Amount
R&R	REMOVE AND REPLACE FRONT SWAY BAR BUSHINGS			C	99564	65.00
Part	Part Description	Req	Bin	Type	Price	Amount
20204AG011	RUB BUSH ARM F R	2	B01D08	CRO	42.99	85.98
Request Total						150.98

Request	Description	Job	Type
WA	ALIGNMENT	4	C
Labour	Description	Type	CSR Amount
WA	ALIGNMENT	C	99564 119.95
Request Total			119.95

Request	Description	Job	Type
R&R	REMOVE AND REPLACE TRANSMISSION COOLER LINE CLAMP AND TOP UP FLUID	5	C
Labour	Description	Type	CSR Amount
R&R	REMOVE AND REPLACE TRANSMISSION COOLER LINE CLAMP AND TOP UP FLUID	C	99564 65.00

ALL ITEMS ARE SUBJECT TO P.S.T.

P.S.T. # 1101-3732

THANK YOU FOR BRINGING YOUR CAR TO US FOR SERVICE

O U T	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER.
	DATE: _____ SIGNATURE: _____

PARTS AND
SERVICE HOURS:
MONDAY—FRIDAY
7:30AM—5:00 PM



EST# 14849

**SERVICE ESTIMATE
CUSTOMER COPY**



Printed 03/28/2022 11:14:59 AM

User KAYDEE Page 2

Customer No 71185	Advisor Kaydee Zielke (99564)	Est Date 03/28/2022	Tag
Location	Expiry Date 04/27/2022		
KTUNAXA NATION COUNCIL HEALTH DEPT 220 CRANBROOK ST N CRANBROOK, BC V1C 3R2			
License No 919RJF	Odometer In 187753	Stock No S09138	Delivery Date 08/13/2009
Year 2009	Make SUBARU	Model IMPREZA	InServ Date 08/13/2009
Vehicle ID No JF1GH61659H809138	Selling Dealer	Model No	Colour WHITE
Home (250) 420-2756		Bus (250) 420-2756	
Cell (250) 464-5286		Today	
Email accountspayable@ktunaxa.org		Extended Warranty	

Part	Part Description	Req	Bin	Type	Price	Amount
SCI810004	SLL COOLANT/AF CASE 12X1 LITRE	1	BACKRO	CRO	12.99	12.99
Request Total						77.99

Request	Description				Job	Type
R&R	REMOVE AND REPLACE REAR WIPER				6	C
Labour	Description			Type	CSR	Amount
R&R	REMOVE AND REPLACE REAR WIPER			C	99564	0.00
Part	Part Description	Req	Bin	Type	Price	Amount
SOA591R616	16" REAR WIPER BLADE	1		CRO	13.99	13.99
Request Total						13.99

Request	Description				Job	Type
R&R	REMOVE AND REPLACE DRIVE BELT (NO LABOR CHARGE IF DONE WITH TIMING BELT)				7	C
Labour	Description			Type	CSR	Amount
R&R	REMOVE AND REPLACE DRIVE BELT (NO LABOR CHARGE IF DONE WITH TIMING BELT)			C	99564	65.00
Part	Part Description	Req	Bin	Type	Price	Amount
809218370	V BELT	1	WALL2	CRO	27.99	27.99
Request Total						92.99

Labour	1,003.95
Parts	757.88
Supplies	36.18
Env Fee	0.00
Sub-Total	1,798.01
GST	89.90
PST	125.86
Total Estimate	2,013.77

ALL ITEMS ARE SUBJECT TO P.S.T.

P.S.T. # 1101-3732

THANK YOU FOR BRINGING YOUR CAR TO US FOR SERVICE

O U T	INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER.
	DATE: _____ SIGNATURE: _____

**PARTS AND
SERVICE HOURS:**
MONDAY—FRIDAY
7:30AM—5:00 PM



Subaru

flexiNET

24

www.ImportAutoGroup.com
878 TND





HOW'S MY DRIVING?
1-888-480-2464

24

www.Import Auto Group .com
Beautiful British Columbia
878 TND
AUG 2021
CRANBROOK

SUBARU
OF CRANBROOK
CRANBROOK, B.C.

IMPREZA